



NETWORK SURVEILLANCE SERVER

# **NSR-500 series**

Security Update 1501151 Patch Instructions

2015/01/29

## 【Overview】

The security is improved.

### Note

This patch loses effect after updating of NSR software. Please be sure to install this patch file after updating NSR software.

## 【Preparation】

Please prepare the followings.

- NSR Patch File : NSR-500-patch\_SecurityUpdate-1501151-1-20150115.i386.rpm
- NSR-500

This patch file is available only for the NSR version of v1.5.1 or more. Prior to the installation, confirm the version of NSR. When it is lower, upgrade it to v1.5.1 or more first.

## 【Install Procedure】

1. Connect a monitor and a USB keyboard/mouse with NSR.

### Note

Please use a general USB keyboard/mouse. Devices with particular keys and wheels may be unable to use.

2. Write the patch file in a USB memory, and install it. Please see user guide regarding installing patch file.

### Note

After installing this patch, NSR is rebooted.

## 【Confirmation】

You can confirm the updated version via the logon screen after the patch installation. Click [Information] - [Detail Information], and confirm that “SecurityUpdate-1191107 SecurityUpdate-1501151” is added into “Patch Version” .

## Detail Information

Software Version:1.5.1.8

### Server Software

NSR GUI:3.5.0.15

Record Server:5.5.0.15

Central Server:1.5.100

Download Server:1.4.2

Event Action Server:1.0.5.4

HW Control Server:1.4.0.3

libRsmCore:2.22.15

libcsc:1.5.100

libdsc:1.4.2

libeasc:1.5.4

libmetadata:1.6.1

### Server Platform

Model Name:NSR-500

Serial Number:1303567

SDK Version:1.00.0000.31

Patch version:

SecurityUpdate-1191107 SecurityUpdate-1501151

Close